

CLASSIFIED MESSAGE

ROUTING

DATE

S E C R E T

0125Z 18 DEC 63

TO : DIRECTOR

FROM : KWCABLE

ACTION:

INFO : OSA 1-15

TOR: 0259Z 18 DEC 63

ROUTINE

OXCART

IN 54966

TO ADIC

INFO

CITE CABLE 3115

OXCART MEDICAL

1. FOLLOWING COMMENTS CONCERN DUAL SUIT FLIGHT OF [REDACTED] 50X1
 AND [REDACTED] IN ARTICLE 124 ON 17 DEC 63. TAKEOFF TIME 1700L. 50X1
 TIME OF FLIGHT 2:04. TIME IN SUIT 3:30.

A. [REDACTED] BODY OF SUIT TOO SHORT CAUSING PRESSURE ON 50X1
 SHOULDERS. COCKPIT LIGHTS AND TANKER LIGHTS CAUSED VISOR
 REFLECTION PROBLEM.

B. [REDACTED] DIFFICULTY REACHING STOCK COMPONENTS WITH 50X1
 PRESSURE SUIT GLOVES.

2. BOTH PILOTS COMPLAINED OF PARACHUTE/SEAT KIT DISCOMFORT.

END OF MESSAGE

DOCUMENT NO.

NO CHANGE IN CLASS. ☒☐ DECLASSIFIED

CLASS. CHANGED TO: TS S C 2011

NEXT REVIEW DATE:

AUTH: HR 70-2

DATE: 16/9/81 REVIEWER: 064540

S E C R E T

GROUP 1
 Excluded from automatic
 downgrading and
 declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.